

# Appendix I – Preliminary Geotechnical Report prepared by HD Geo





**TAMAHERE  
COUNTRY  
CLUB**

**PRELIMINARY  
GEOTECHNICAL  
REPORT**

PROJECT NO: HD2812  
SANDERSON GROUP  
REFERENCE: PCR-1  
01 MAY 2023

## Executive summary

Sanderson Group have engaged us to undertake a preliminary geotechnical assessment for the site located at 56, 70, 82 and 92 Tamahere Drive, Tamahere. They propose to remove all existing dwellings and create a future retirement complex. This report is intended to help guide planning for future development and may be submitted to the Waikato District Council in support of the resource consent application.

We believe the site is suitable for the proposed development subject to the geotechnical recommendations within this report.

## Our scope included

- a desktop study of the site including a review of geology maps, aerial photography, contour maps, and the NZ Geotechnical Database (NZGD)
- a site walkover to identify geohazards onsite
- an intrusive investigation which included:
  - 5 hand augers (HA) to 3.0 m depth with strength testing
  - 5 soakage tests (ST) up to 2.0 m depth
- a natural hazards assessment, including a quantitative liquefaction assessment
- a high level earthworks discussion
- a indicative pavement conditions
- a discussion of foundation conditions

## Our key findings and outcomes were

- materials encountered on site within the hand augers (silts and sands) were consistent with the mapped Hinuera Formation
- based on the ground conditions encountered, the site does not meet the requirements for 'good ground' in accordance with NZS 3604:2011 due to loose soils (in the upper 2.2 m)
- we encountered groundwater within HA05 at 2.4 m below ground level. Given the elevated nature of the site (RL 48) above the gully system (RL 29) to the east, we expect the water we found was perched and global groundwater is deeper.
- based on the results of the testing, soakage is likely to be a viable method of disposing stormwater
- the site lies within performance level L0 (insignificant anticipated liquefaction effects)
- lateral spreading under liquefied conditions is unlikely at the site due to deep groundwater (> 43 m) and distance to the free face (40 m)
- testing shows that the soils along Site 1 and Site 2 are generally loose to medium dense within the upper 1.0 m and a CBR of 2 to 3 is representative of the natural soils

## Our recommendations are that:

Given the low strength soils, foundations will need to be designed for reduced bearing. We expect suitable foundations to be:

- shallow excavation and re-compaction of the soils in the upper 0.5 m to 1.0 m bgl
- a stiffened raft foundation (ie Firth X-Pod or similar) designed for low bearing soils

Additional input will be required for elements of the future development including:

- Review of plans and updating of this report
- Further testing and specific assessment for bearing capacity and settlement for any structures
- Engineered foundation design for any structures

---

## Contents

---

Executive summary .....	1
Introduction .....	4
Scope.....	4
Site description .....	4
Desk study.....	5
Site investigation.....	5
Ground conditions .....	6
Groundwater.....	6
Geotechnical assessment.....	7
Liquefaction .....	8
Earthworks .....	10
Pavements.....	10
Foundations .....	11
Future works .....	11
Limitation .....	11
Appendix A .....	A
Drawing 01: Site plan .....	A
Appendix B .....	B
Historical aerial images .....	B
Appendix C .....	C
Drawing 02: Site investigation plan .....	C
Investigation data .....	C
Appendix D.....	D
Liquefaction assessment.....	D

PREPARED BY: **Retha Richards**

REVIEWED BY **Kent Morgan, CPEng**



GEOTECHNICAL ENGINEER

Retha@hdgeo.co.nz

Tel 027 309 4555



GEOTECHNICAL ENGINEER

Kent@hdgeo.co.nz

---

## Introduction

---

Sanderson Group have engaged us to undertake a preliminary geotechnical assessment for the site located at 56, 70, 82 and 92 Tamahere Drive, Tamahere. They propose to remove all existing dwellings and create a future retirement complex. This report is intended to help guide planning for future development and may be submitted to the Waikato District Council in support of resource consent application.

We believe the site is suitable for the proposed development subject to the geotechnical recommendations within this report.

---

## Scope

---

The scope of our assessment included:

- a desktop study of the site including a review of geology maps, aerial photography, contour maps, and the NZ Geotechnical Database (NZGD)
- a site walkover to identify geohazards onsite
- an intrusive investigation which included:
  - 5 hand augers (HA) to 3.0 m depth with strength testing
  - 5 soakage tests (ST) up to 2.0 m depth
- a natural hazards assessment, including a quantitative liquefaction assessment
- a high level earthworks discussion
- a indicative pavement conditions
- a discussion of foundation conditions

---

## Site description

---

The site consists of 2 areas which are 56 and 70 Tamahere Drive ('Site 1') and 82 and 92 Tamahere Drive ('Site 2'). A plan of the site is shown in Drawing 01 in Appendix A.

The site is bounded by Tamahere Drive to the east and new residential development to the north and west of Site 1 and the north of Site 2.

Site 1 is legally described as Lot 1 DPS 59441 and Lot 1 DPS 80372 and covers an area of approximately 1.8 ha, generally covered with pasture and existing dwellings.

Site 2 is legally described as Lot 1 DP 565970 and PT Lot 11 DP9747 and covers an area of approximately 4 ha, generally covered with a tree plantation, existing dwellings, and other structures.

The overall site is relatively flat. The nearest sloping ground, which is a gully system, is located approximately 30 m to the east.

---

## Desk study

---

We completed a desktop study prior to the site investigation to identify areas of interest. This included a review of geology maps<sup>1</sup>, New Zealand Geotechnical Database (NZGD)<sup>2</sup>, and historical<sup>3</sup> and recent<sup>4</sup> aerial images.

## Geological setting

The geologic map of the area shows the site is underlain by Late Pleistocene river deposits of the Hinuera Formation. The Hinuera Formation is described as cross-bedded pumice sand, silt and gravel with interbedded peat.

## Aerial photography

We have reviewed the historic and recent aerial images to identify past land uses and any geomorphic changes at the site or surrounding areas. Aerial photos are provided in Appendix B.

The aerial images indicated:

- the site has remained largely as undeveloped farmland since 1943
- between 1953 and 1973, the tree plantation has been established, as well as additional dwellings
- between 2021 and 2022, the new residential development is in progress to the north and west

From the review, there appears to be no significant changes to the geomorphology at the site or surrounding area over the period reviewed.

## NZGD

We have reviewed the NZ Geotechnical Database (NZGD) to determine whether ground investigations have been conducted at or near the site.

2 hand augers and 2 cone penetration tests were completed to the south of Site 1. 15 hand augers and 11 cone penetration tests were completed to the north of Site 2.

The soil logs found a mixture of clay, silt and sand consistent with the Hinuera Formation. Groundwater was encountered in hand augers between 3.0 m and 3.9 m below ground level. No groundwater was recorded for the CPTs.

---

## Site investigation

---

Our onsite investigation was completed on 29 March and 04 April 2023. We assessed ground conditions by reviewing available testing (13 cone penetration tests) on, or near the site and by conducting 5 hand augers (HA) with strength testing and 5 soakage tests (ST). In-situ strength testing was undertaken using a shear vane and dynamic cone penetrometer test (DCP). Our intrusive site investigation found ground conditions that were consistent with the published geology.

---

<sup>1</sup>1:250,000 Geological Map of New Zealand (QMAP). *New Zealand Geology Web Map*. GNS, 2013. <http://data.gns.cri.nz/geology/>

<sup>2</sup>New Zealand Geotechnical Database. <https://www.nzgd.org.nz/default.aspx>

<sup>3</sup>Sourced from <http://retrolens.nz> and licensed by LINZ CC-BY

<sup>4</sup>Google Earth Pro

## Ground conditions

The hand augers had a target depth of 3.0 m which was achieved for all tests. The test location plan and soil logs are included in Appendix C.

The materials encountered on site within the hand augers were consistent with the mapped Hinuera Formation. The ground conditions found during the hand auger investigation are summarised below.

For Site 1, the ground conditions encountered were:

- topsoil up to between 0.2 m and 0.5 m below ground level (bgl);
- sand and silt, with interbedded lenses of clay
  - peak shear strength ranged between 134 and 140 kPa, showing the cohesive material to be very stiff
  - DCP values ranged between 2 to 6 blows per 100 mm showing the material to be loose to medium dense

For Site 2, the ground conditions encountered were:

- topsoil up to between 0.2 m and 0.3 m below ground level (bgl);
- sand and silt, with interbedded lenses of clay
  - peak shear strengths ranged between 135 and 209+ kPa, showing the cohesive material to be very stiff to hard
  - DCP values ranged between 1 to 12 blows per 100 mm showing the material to be very loose to dense

## Groundwater

We encountered groundwater within the hand augers at 2.4 m below ground level within HA05. The dynamic pore pressure response within the CPTs indicates that there is perched water within near surface soil layers (top 3 m to 5 m), but consistent response wasn't observed to the depth of testing (43 m).

Given the elevated nature of the site (RL 48) above the gully system (RL 29) to the east, we expect the water we found was perched and global groundwater is deeper. We have used a conservative groundwater level of 3.0 m bgl for our assessment below.

## Soakage testing

We undertook falling head permeability tests within the proposed Site 1 and Site 2 to determine the capacity of the soils to receive concentrated stormwater flows. The falling head tests were undertaken generally in accordance with the Regional Infrastructure Technical Specifications (RITS) and the NZBC E1 Method.

Soakage testing was undertaken in the following locations:

- 2 within Site 1 boundary
- 3 within Site 3 boundary

The testing was undertaken within a mixture of silt and sand interpreted as Hinuera Formation. Results of the falling head permeability tests are in Appendix C.



**Table 1: Summary of soakage results**

Description	Location	Design soakage (mm/hr)*
ST01	Site 1, west of existing dwelling	1500 +
ST02	Site 1, north of existing dwelling	165
ST03	Site 2, near northern corner	280
ST04	Site 2, north-west of existing dwelling	220
ST05	Site 2, near southern corner	200

\* a 50% reduction rate has been applied as per the RITS<sup>5</sup>

The minimum soakage threshold of 150 mm/hr specified in the RITS manual is achieved for all tests. It is recommended that a design rate of 1500 mm/hr is adopted for ST01.

Based on the soakage rates, disposal of stormwater via soakage is viable for Site 1 and Site 2.

---

## Geotechnical assessment

---

The ground conditions encountered onsite are generally suitable for development, so long as the geotechnical recommendations below are incorporated into the design and best practice construction methods are adopted. There are no major hazards identified that preclude future development of the site.

### Natural hazards

We have carried out a natural hazards assessment. As per Section 106 of the Resource Management Act, we consider the site to have no significant risk of the following natural hazards:

- **Earthquake and liquefaction:** liquefaction is assessed as insignificant for the site (see 'Liquefaction' section below). The general earthquake hazard in the area is low with no active faults nearby.
- **Volcanic, geothermal, or sedimentation activity:** The site is not near any known sources of these hazards.
- **Land slips or slope instability:** The site is near level and there is no risk of instability.
- **Erosion:** we observed no indications of erosion during the site walkover and as the site is near level and there are no free faces nearby, we consider the risk of erosion damage to the site as low.
- **Flooding:** The site is not mapped within the Waikato Regional Hazards Portal<sup>6</sup> as being at risk to flooding.
- **Expansive soils:** We did not encounter natural soils with high plasticity in the near-surface soils during our site investigation. Risk of damage caused by expansive soils on the site is low.
- **Subsidence:** The risk of the site to general subsidence is low (refer to 'Foundations' section below).

---

<sup>5</sup> 'Regional Infrastructure Technical Specification' v1.0, Waikato Local Authority Shared Services, dated May 2018.

<sup>6</sup> Waikato Regional Hazards Portal, River Flooding

<https://waikatoregion.maps.arcgis.com/apps/MapSeries/index.html?appid=f2b48398f93146e8a5cf0aa3fddce92c>

**Table 2: Natural hazards risk matrix**

RISK ASSESMENT MATRIX		LIKELIHOOD				
		Very unlikely	Unlikely	Possible	Likely	Very likely
POTENTIAL CONSEQUENCES	Severe					
	Moderate					
	Minor	- Flooding - Landslips or slope instability	- Liquefaction - Lateral spreading			
	Negligible	- Earthquake - Volcanic, geothermal or sedimentation activity - Expansive soils - Erosion - Subsidence				

## Liquefaction

We have undertaken a quantitative liquefaction assessment using the CPT data obtained from NZGD. The assessment has been undertaken in accordance with the NZGS and MBIE guidelines<sup>7</sup>. Outputs from the CPT analysis are included in Appendix C. The liquefaction assessment is included in Appendix D.

### Assessment inputs

We completed a screening analysis using the CPT data for a 1 in 500-year (ULS) and 1 in 25-year (SLS) design events. The test results were analysed using the proprietary software CLIQ (Geologismiki) and engineering calculations in accordance with recent NZGS guidelines.

The design earthquake for the analysis of liquefaction susceptibility has been taken from Module 1: Overview of the guidelines<sup>8</sup> of MBIE and NZGS. Input parameters for the analysis are listed below:

**Table 2: Input parameters used for our quantitative liquefaction assessment**

Parameter	Input
Site seismic classification <sup>9</sup> :	Class D (deep soils)*
Structural importance level <sup>10</sup> :	Importance level 2 – residential
Peak ground acceleration <sup>11</sup> :	0.06 g (SLS) for a 1 in 25-year event 0.25 g (ULS) for a 1 in 500-year event, 5.9 magnitude earthquake
Groundwater depth:	3.0 m bgl
Limit depth:	10 m from current ground level (for indexing)

\*The site is Class D, however following Module 1 requirements, the PGA is based on Class C conditions.

<sup>7</sup> Ministry of Business Innovation and Employment (MBIE) / New Zealand Geotechnical Society (NZGS). Module 3: Identification, assessment, and mitigation of liquefaction hazards. Dated November 2021.

<sup>8</sup> Ministry of Business Innovation and Employment (MBIE) / New Zealand Geotechnical Society (NZGS). Module 1: Overview of the guidelines. Dated November 2021.

<sup>9</sup> NZS 1170.5:2004. *Structural design actions – Earthquake Actions (New Zealand)*. SANZ

<sup>10</sup> NZS 1170.0:2002. *Structural design actions – General Principles*. SANZ

<sup>11</sup> GNS Science: National Seismic Hazard Model. <https://nshm.gns.cri.nz/HazardCurves>.

### *Liquefaction susceptibility*

The susceptibility of a site to liquefaction is a combination of the expected earthquake shaking for the required design return period, the soil types and their strength/density state, and the groundwater conditions at the site. There are several measures of a site's overall susceptibility to liquefaction including liquefaction potential index (LPI), liquefaction severity number (LSN), ground surface settlement, and lateral spreading.

The CPTs have been assessed under ULS conditions with the analysis limited to 10 m depth for the screening assessment in accordance with the guidelines. Beneath 10 m the effects of liquefaction may contribute to global settlements however are unlikely to have significant surface expression. Liquefaction should be considered below 10 m if deep foundations are proposed.

### **Serviceability Limit State (SLS) Earthquake**

An SLS earthquake is an event after which there is high expectation that the building or structure can be used as intended without repair or with minimal repair. The assessment showed that under SLS conditions there is no liquefaction damage expected at the site.

### **Ultimate Limit State (ULS) Earthquake**

A ULS earthquake is an event after which a building should retain its integrity to allow safe evacuation of people but is likely to be severely damaged and may not be repairable. The assessment showed that under ULS conditions there is a liquefaction hazard at the site.

Under ULS conditions, our assessment indicated:

- between 0 and 25 mm of predicted vertical settlement
- Liquefaction Potential Index (LPI) of between 0 and 1 (insignificant risk)
- Liquefaction Severity Number (LSN) of between 0 and 5 (insignificant expression expected)
- limited potentially liquefiable layers across the entire soil profile below the ground water level (3.0 m)

### *Groundwater sensitivity check*

We have assessed the site with the encountered groundwater conditions. To understand the overall liquefaction risk, we have completed a sensitivity analysis on the groundwater conditions and assumed a peak high groundwater table of 1.0 m higher (2.0 m below ground level).

The sensitivity analysis predicted:

- slight increase in overall vertical settlement of 5 to 10 mm
- Liquefaction Potential Index (LPI) between 0 to 2 (insignificant to mild risk)
- Liquefaction Severity Number (LSN) between 1 and 9 (insignificant to mild expression expected)

Under a higher groundwater level, the site performance will increase to L1 (mild anticipated liquefaction effects).

### *Site performance level*

Our assessment indicates that the site lies within performance level L0 to L1 (insignificant to mild anticipated liquefaction effects) in accordance with Table 5.1 of the latest MBIE and NZGS guidelines<sup>12</sup>. This performance level is defined as:

- liquefaction occurs in layers of limited thickness
- negligible ground deformation and very small total and differential settlements

### *Lateral spreading*

Lateral spreading is a phenomenon where liquefied material allows the soil above to move laterally towards a free face, such as a stream bank. There is a free face towards the east of the site approximately 40 m away.

Lateral spreading under liquefied conditions is unlikely at the site due to the estimated depth (> 43 m) to groundwater and the distance to the free face.

## Earthworks

There is no current design for cut to fill at the site however, we would expect that earthworks will be required to create level or near-level building platforms and gentle road alignments.

Any earthworks with fill depths greater than 0.6 m, or any fill relied on for the support of foundations, should only be undertaken in accordance with NZS4431:2022 “Code of practice for Earthfill for Residential Development” and with input by a suitably qualified engineer.

The granular materials of the Hinuera Formation present across the site, are suitable for reuse as earthwork material. During very dry weather, materials can become dry of optimum, and wetting can be needed to condition them.

In general, we expect any externally sourced sand fill to be suitable for use as fill if placed in accordance with NZS4431:2022. Externally sourced clay materials will require further laboratory testing, assessment and specification.

## Pavements

Currently the road grading design has not been completed and so subgrade levels are not known. Our testing shows that the soils along Site 1 and Site 2 are generally loose to medium dense within the upper 1.0 m and a CBR of 2 to 3 is representative of the natural soils.

During design and construction, testing will be needed to confirm the subgrade and low strength areas may need undercutting. Once the design of the subdivision is complete, testing should be undertaken, and the pavement requirements confirmed.

---

<sup>12</sup> Module 3: Identification, assessment and mitigation of liquefaction hazards. Prepared by Ministry for the Environment and Ministry of Business, Innovation and Employment, dated November 2021.

## Foundations

Based on the ground conditions encountered during the site investigation, the site does not meet the requirements for 'good ground' in accordance with NZS 3604:2011 due to loose soils. Given the low strength soils, foundations will need to be designed for reduced bearing.

We expect suitable foundations to be:

- shallow excavation and re-compaction of the soils in the upper 0.5 m to 1.0 m bgl
- a stiffened raft foundation (ie Firth X-Pod or similar) designed for low bearing soils

Further assessment and refining of these recommendations (i.e. available bearing capacity, and anticipated settlement under the proposed building loads) will be needed for the design phase of the development. Foundation options for future buildings will need to be specifically assessed in accordance with geotechnical guidelines.

---

## Future works

Based on our assessment, the site is geotechnically suitable for the proposed development, subject to the recommendations within this report. Additional geotechnical investigation and assessment are needed to confirm ground conditions and recommendations for developing the site. Additional input will be required for elements of the future development including:

- Review of plans and updating of this report to support building consent
- Further testing and specific assessment for bearing capacity and settlement for any structures
- Engineered foundation design for any structures

---

## Limitation

This report has been prepared for our client, Sanderson Group, and their professional advisers, for the purposes detailed above and may not be relied on by any other party for any other purposes. This report contains a preliminary assessment to provide information about current ground conditions and likely requirements for developing the site based on a site walkover and testing in discrete locations. Further testing and assessment are required during the development of the site. Inferences about the conditions at the site have been made based on the testing undertaken and our understanding of the geological environment in which the site lies.


We recommend that HD Geo is engaged to undertake further testing and assessment for building consent, and to observe works during the site preparation.


# APPENDIX A

Drawing 01: Site plan



**LEGEND**

Site 1 boundary 

Site 2 boundary 

**PROJECT:** Tamahere Country Club

**PROJECT No:** HD2812

**CLIENT:** Sanderson Group

**TITLE:** Site investigation plan

**SCALE:** N/A

**Drawing No:** 01

**Drawing By:** RR

**Rev no:**

1	initial

# APPENDIX B

Historical aerial images





Figure 1. Historical Imagery from 1943. Approximate site location marked in yellow. (Imagery from <http://retrolens.nz/>)



Figure 2. Historical Imagery from 1953. Approximate site location marked in yellow. (Imagery from <http://retrolens.nz/>)



Figure 3. Historical Imagery from 1973. Approximate site location marked in yellow. (Imagery from <http://retrolens.nz/>)



Figure 4. Historical Imagery from 1979. Approximate site location marked in yellow. (Imagery from <http://retrolens.nz/>)



Figure 5. Historical Imagery from 1995. Approximate site location marked in yellow. (Imagery from <http://retrolens.nz/>)



Figure 6. Historical Imagery from 2008. Approximate site location marked in yellow. (Imagery from Google Earth Pro)



Figure 7. Historical Imagery from 2015. Approximate site location marked in yellow. (Imagery from Google Earth Pro)





Figure 8. Historical Imagery from 2021. Approximate site location marked in yellow. (Imagery from Google Earth Pro)








Figure 9. Historical Imagery from 2022. Approximate site location marked in yellow. (Imagery from Google Earth Pro)

# APPENDIX C

Drawing 02: Site investigation plan  
Investigation data



**LEGEND**

- Site 1 boundary 
- Site 2 boundary 
- Hand Auger (HA) 
- Soakage Test (ST) 
- Cone penetration test (CPT) - NZGD 

**PROJECT:** Tamahere Country Club

**PROJECT No:** HD2812

**CLIENT:** Sanderson Group

**TITLE:** Site investigation plan

**SCALE:** N/A

**Drawing No:** 02

**Drawing By:** RR

**Rev no:**

1	initial



# INVESTIGATION LOG

**Job No.:** HD2812  
**No.:** HA01  
**Date:** 04.04.23  
**Logged By:** SW  
**Checked By:** RR

**Client:** Tamahere Country Club  
**Project:** Tamahere Country Club PGR  
**Location:** -  
**Co-ordinates:** 1807557mE, 5809993mN  
**Elevation:** Ground

Geology	Geological Interpretation <small>(refer to separate Geotechnical and Geological Information sheet for further information)</small>	Depth (m)	Legend	Scala Penetrometer <small>(Blows / 100 mm)</small>	Vane Shear Strength (kPa) <small>Vane: 2639</small>	Water
				2 4 6 8 10 12 14 16 18	50 100 150 200 250	
Topsoil	Sandy TOPSOIL; greyish brown. Dry; sand, fine.	0.0 - 0.2	TS	4		
Hinuera Formation	Sandy SILT; light brown. Medium dense; moist; sand, fine.	0.2 - 0.8	TS	4	122	
		0.4 - 0.5	TS	3	18	
		0.5 - 0.6	TS	4		
		0.6 - 0.7	TS	5	181	
		0.7 - 0.8	TS	6	33	
	Silty CLAY, with some sand; brown. Hard; moist; sand, medium, Quartz.	0.8 - 1.0	TS	4	208+	
		1.0 - 1.1	TS	4		
	SAND, with trace clay; brown. Medium dense; moist; sand, medium.	1.1 - 1.4	TS	3		
		1.2 - 1.3	TS	4		
		1.3 - 1.4	TS	6		
	1.4 - 1.6	TS	6			
Silty CLAY, with minor sand; light grey. Very stiff; moist; moderate plasticity, sensitive to moderately sensitive; sand, fine.	1.6 - 2.4	TS	5			
	1.6 - 1.7	TS	2			
	1.7 - 1.8	TS	2	134		
	1.8 - 1.9	TS	2	33		
	1.9 - 2.0	TS	2			
	2.0 - 2.1	TS	2	140		
	2.1 - 2.2	TS	4	30		
	2.2 - 2.3	TS	4			
	2.3 - 2.4	TS	3	148		
	2.4 - 2.5	TS	3			
SAND, with minor silt; light grey. Medium dense; moist; sand, fine.	2.5 - 3.0	TS	4	56		
	2.5 - 2.6	TS	3			
	2.6 - 2.7	TS	4			
	2.7 - 2.8	TS	4			
	2.8 - 2.9	TS	4			
Silty CLAY; light grey. Very stiff; moist; moderate plasticity, moderately sensitive.	2.9 - 3.0	TS	3	134		
	3.0 - 3.1	TS	3	45		

Groundwater Not Encountered

Photo	Remarks
	End of HA at 3.0 meters_ Target depth achieved.
<div style="display: flex; justify-content: space-between;"> <div style="width: 30%;"> <p><b>Shear Vanes</b></p> <ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Remoulded</li> </ul> </div> <div style="width: 30%;"> <p><b>Water</b></p> <ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 1px solid black; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 1px solid black; border-bottom: 1px solid black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 1px solid black; border-right: 1px solid black; margin-right: 5px;"></span> In flow</li> </ul> </div> <div style="width: 30%;"> <p><b>Investigation Type</b></p> <ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input type="checkbox"/> Machine Borehole</li> </ul> </div> </div>	

Generated with CORE-GS by Gerooc - 17/04/2023 13:36:13







# INVESTIGATION LOG

Job No.: HD2812  
 No.: HA03  
 Date: 29.03.23  
 Logged By: TD  
 Checked By: RR

Client: Tamahere Country Club  
 Project: Tamahere Country Club PGR  
 Location: -  
 Co-ordinates: 1807665mE, 5809655mN  
 Elevation: Ground



Groundwater Not Encountered

Photo	Remarks						
	<p>End of log at 3.0m. Target depth.</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 33%;"><b>Shear Vanes</b></td> <td style="width: 33%;"><b>Water</b></td> <td style="width: 33%;"><b>Investigation Type</b></td> </tr> <tr> <td> <ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; border-style: dashed; margin-right: 5px;"></span> Remoulded</li> </ul> </td> <td> <ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; border-bottom: 2px solid black; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px solid black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-right: 2px solid black; margin-right: 5px;"></span> In flow</li> </ul> </td> <td> <ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input type="checkbox"/> Machine Borehole</li> </ul> </td> </tr> </table>	<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>	<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; border-style: dashed; margin-right: 5px;"></span> Remoulded</li> </ul>	<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; border-bottom: 2px solid black; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px solid black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-right: 2px solid black; margin-right: 5px;"></span> In flow</li> </ul>	<ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input type="checkbox"/> Machine Borehole</li> </ul>
<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>					
<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; border-style: dashed; margin-right: 5px;"></span> Remoulded</li> </ul>	<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; border-bottom: 2px solid black; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px solid black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-right: 2px solid black; margin-right: 5px;"></span> In flow</li> </ul>	<ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input type="checkbox"/> Machine Borehole</li> </ul>					

Generated with CORE-GS by Gerooc - 17/04/2023 13:36:14




# INVESTIGATION LOG

Job No.: HD2812  
 No.: HA04  
 Date: 04.04.23  
 Logged By: SW  
 Checked By: RR

Client: Tamahere Country Club  
 Project: Tamahere Country Club PGR  
 Location: -  
 Co-ordinates: 1807520mE, 5809666mN  
 Elevation: Ground

Geology	Geological Interpretation <small>(refer to separate Geotechnical and Geological Information sheet for further information)</small>	Depth (m)	Legend	Scala Penetrometer <small>(Blows / 100 mm)</small>	Vane Shear Strength (kPa) <small>Vane: 2639</small>	Water	
				2 4 6 8 10 12 14 16 18	50 100 150 200 250		
Topsoil	TOPSOIL; brown. Moist.	0.0 - 0.2	TS	3			
Hinuera Formation	Silty CLAY; light brown streaked orange. Hard; moist; low to moderate plasticity, sensitive.	0.2 - 0.4	x	2	202		
	SAND, with minor silt; light brown. Loose to medium dense; moist; sand, fine to medium.	0.4 - 0.6	x	3		45	
		0.6 - 0.8	x	3			
		0.8 - 1.0	x	3			
		1.0 - 1.2	x	2			
		1.2 - 1.4	x	5			
	SAND, with some silt; light brown. Medium dense; moist to wet; uniformly graded; sand, fine.	1.4 - 1.6	x	6			
		1.6 - 1.8	x	7			
		1.8 - 2.0	x	6		202	
		2.0 - 2.2	x	3			
		2.2 - 2.4	x	3			
	SILT, with some sand; light grey. Medium dense to dense; wet; sand, fine.	2.4 - 2.6	x	4			
		2.6 - 2.8	x	3			
		2.8 - 3.0	x	10			
	SAND, with some silt; light grey. Medium dense to dense; wet; uniformly graded; sand, fine.	3.0 - 3.2	x	6			
SAND, with some silt; light grey. Medium dense to dense; wet; uniformly graded; sand, fine.	3.2 - 3.4	x	3				
SAND, with some silt; light grey. Medium dense to dense; wet; uniformly graded; sand, fine.	3.4 - 3.6	x	3				
SAND, with trace silt; grey. Medium dense to dense; wet to saturated; well graded; sand, fine to coarse.	3.6 - 3.8	x	4				
SILT, with some sand; light grey. Medium dense to dense; wet; sand, fine.	3.8 - 4.0	x	9				
SILT, with some sand; light grey. Medium dense to dense; wet; sand, fine.	4.0 - 4.2	x	10				
SILT, with some sand; light grey. Medium dense to dense; wet; sand, fine.	4.2 - 4.4	x	8				
SAND, with trace silt; grey. Medium dense to dense; wet to saturated; well graded; sand, fine to coarse.	4.4 - 4.6	x	6				
SAND, with trace silt; grey. Medium dense to dense; wet to saturated; well graded; sand, fine to coarse.	4.6 - 4.8	x	5				
EOH: 3.00 m	4.8 - 5.0	x	7				
	5.0 - 5.2	x	7				

Groundwater Not Encountered

Photo	Remarks						
	End of HA at 3.0 meters_ Target depth achieved.						
<table style="width: 100%; border: none;"> <tr> <td style="width: 33%; border: none;"><b>Shear Vanes</b></td> <td style="width: 33%; border: none;"><b>Water</b></td> <td style="width: 33%; border: none;"><b>Investigation Type</b></td> </tr> <tr> <td style="border: none;"> <ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Remoulded</li> </ul> </td> <td style="border: none;"> <ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px solid black; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px dashed black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px dotted black; margin-right: 5px;"></span> In flow</li> </ul> </td> <td style="border: none;"> <ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input type="checkbox"/> Machine Borehole</li> </ul> </td> </tr> </table>		<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>	<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Remoulded</li> </ul>	<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px solid black; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px dashed black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px dotted black; margin-right: 5px;"></span> In flow</li> </ul>	<ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input type="checkbox"/> Machine Borehole</li> </ul>
<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>					
<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Remoulded</li> </ul>	<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px solid black; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px dashed black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border-left: 2px dotted black; margin-right: 5px;"></span> In flow</li> </ul>	<ul style="list-style-type: none"> <li><input checked="" type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input type="checkbox"/> Machine Borehole</li> </ul>					


Generated with CORE-GS by Gerooc - 17/04/2023 13:36:16



# INVESTIGATION LOG

**Job No.:** HD2812  
**No.:** HA05  
**Date:** 29.03.23  
**Logged By:** TD  
**Checked By:** RR

**Client:** Tamahere Country Club  
**Project:** Tamahere Country Club PGR  
**Location:** -  
**Co-ordinates:** 1807433mE, 5809572mN  
**Elevation:** Ground



2.4 m

▼

**Photo**

**Remarks**



End of log at 2.7m. Could not advance due to hole collapse back to 2.5m.

<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>
<input checked="" type="checkbox"/> Peak	▼ Standing Water Level	<input checked="" type="checkbox"/> Hand Auger
<input checked="" type="checkbox"/> Remoulded	↔ Out flow	<input type="checkbox"/> Investigation Pit
	▽ In flow	<input type="checkbox"/> Machine Borehole



# INVESTIGATION LOG

**Job No.:** HD2812  
**No.:** HA06  
**Date:** 04.04.23  
**Logged By:** SW  
**Checked By:** RR

**Client:** Tamahere Country Club  
**Project:** Tamahere Country Club PGR  
**Location:** -  
**Co-ordinates:** 1807231mE, 5809548mN  
**Elevation:** Ground


Geology	Geological Interpretation <small>(refer to separate Geotechnical and Geological Information sheet for further information)</small>	Depth (m)	Legend	Scala Penetrometer <small>(Blows / 100 mm)</small>	Vane Shear Strength <small>(kPa)</small> <small>Vane: 2639</small>	Water
				2 4 6 8 10 12 14 16 18	50 100 150 200 250	
Topsoil	TOPSOIL; dark blackish brown. Moist.		TS	4		
Hinuera Formation	SAND, with some clay, with trace silt; light brown. Loose to medium dense; moist; sand, fine.	0.2	TS	3	154	
		0.3	TS	2	30	
		0.4	TS	2		
		0.5	TS	3		
	SAND, with minor silt; light grey brown. Very loose to medium dense; moist; sand, fine.	0.6	TS	3	95	
		0.7	TS	1	27	
		0.8	TS	2		
		0.9	TS	3		
		1.0	TS	2		
	SAND; grey. Loose; moist to wet; sand, fine.	1.2	TS	4		
		1.3	TS	2		
	SILT, with some clay and sand; brown grey. Very stiff; wet, sensitive; sand, fine.	1.4	TS	2		
		1.5	TS	4	148	
		1.6	TS	5	30	
	SAND, with trace clay; light brown grey. Medium dense; wet; poorly graded; sand, fine to medium.	1.7	TS	3		
	1.8	TS	4			
	1.9	TS	4			
	2.0	TS	4			
SILT, with some sand; light grey. Medium dense; wet; sand, fine.	2.1	TS	4			
SAND, with trace silt; light grey. Loose to medium dense; wet; poorly graded; sand, fine to medium.	2.2	TS	2			
	2.3	TS	3			
	2.4	TS	5			
SILT, with minor sand; light grey. Medium dense; wet; moderate dilatancy; sand, fine.	2.5	TS	4			
	2.6	TS	8			
SAND; grey. Medium dense to dense; wet; sand, fine to coarse.	2.7	TS	6			
	2.8	TS	6			
	2.9	TS	6			
EOH: 3.00 m	3.0	TS	5			

Groundwater Not Encountered


**Photo**
**Remarks**


End of log at 3.0 meters\_ Target depth achieved.

<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>
<input type="checkbox"/> Peak <input checked="" type="checkbox"/> Remoulded	<input type="checkbox"/> Standing Water Level <input type="checkbox"/> Out flow <input type="checkbox"/> In flow	<input checked="" type="checkbox"/> Hand Auger <input type="checkbox"/> Investigation Pit <input type="checkbox"/> Machine Borehole

	<b>INVESTIGATION LOG</b>		Job No.: HD2812
	Client: Tamahere Country Club		No.: ST01
	Project: Tamahere Country Club PGR		Date: 04.04.23
	Location: -		Logged By: SW
Co-ordinates: 1807470mE, 5809962mN		Checked By: RR	
Elevation: Ground			

Geology	Geological Interpretation <small>(refer to separate Geotechnical and Geological Information sheet for further information)</small>	Depth (m)	Legend	Scala Penetrometer <small>(Blows / 100 mm)</small>								Vane Shear Strength (kPa) <small>Vane:</small>					Water		
				2	4	6	8	10	12	14	16	18	50	100	150	200		250	
Topsoil	Sandy TOPSOIL; dark blackish brown. Moist; sand, medium.	0.0 - 0.2	TS																
		0.2 - 0.4	TS																
Hinuera Formation	SAND, with trace clay; brown. Moist; poorly graded; sand, medium.	0.4 - 0.6	TS																
	SAND; orange brown. Moist; sand, fine.	0.6 - 0.8	TS																
	SAND, with trace clay and silt; light brown. Moist; poorly graded; sand, fine.	0.8 - 1.0	TS																
	Silty CLAY; light grey. Moist to wet; low to moderate plasticity.	1.0 - 1.2	TS																
	SAND, with trace gravel; grey brown. Wet; sand, fine to medium; gravel, fine, subround.	1.2 - 1.4	TS																
	Silty CLAY; light grey. Wet; low to moderate plasticity.	1.4 - 1.6	TS																
	SAND, with some silt; light grey. Wet; sand, fine.	1.6 - 1.8	TS																
	Silty CLAY, with minor sand; light grey. Wet; low to moderate plasticity; sand, fine.	1.8 - 2.0	TS																
EOH: 2.00 m	2.0																		

Photo	Remarks												
	End of log at 2.0 meters_ Target depth achieved.  <table border="0"> <tr> <td><b>Shear Vanes</b></td> <td><b>Water</b></td> <td><b>Investigation Type</b></td> </tr> <tr> <td><input type="checkbox"/> Peak</td> <td><input type="checkbox"/> Standing Water Level</td> <td><input type="checkbox"/> Hand Auger</td> </tr> <tr> <td><input type="checkbox"/> Remoulded</td> <td><input type="checkbox"/> Out flow</td> <td><input type="checkbox"/> Investigation Pit</td> </tr> <tr> <td></td> <td><input type="checkbox"/> In flow</td> <td><input checked="" type="checkbox"/> Machine Borehole</td> </tr> </table>	<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>	<input type="checkbox"/> Peak	<input type="checkbox"/> Standing Water Level	<input type="checkbox"/> Hand Auger	<input type="checkbox"/> Remoulded	<input type="checkbox"/> Out flow	<input type="checkbox"/> Investigation Pit		<input type="checkbox"/> In flow	<input checked="" type="checkbox"/> Machine Borehole
<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>											
<input type="checkbox"/> Peak	<input type="checkbox"/> Standing Water Level	<input type="checkbox"/> Hand Auger											
<input type="checkbox"/> Remoulded	<input type="checkbox"/> Out flow	<input type="checkbox"/> Investigation Pit											
	<input type="checkbox"/> In flow	<input checked="" type="checkbox"/> Machine Borehole											

Generated with CORE-GS by Gerooc - 17/04/2023 13:36:19




<b>Job name</b>	Tamahere Country Club
<b>Job number</b>	HD2812
<b>Date</b>	04/04/2023
<b>Plotted by</b>	SW (RR)
<b>Reviewed by</b>	BS

**Perc test results**  
**ST01**

Calculated in general accordance with E1/VM1 - Surface Water, Section 9.0

**Logger depth:** 2.000 m  
**Ground water depth:** NA m

Notes:



**Recommended design rate**  
**1500 mm/hr**

**Percolation rate calculation:**

Time (Hour)	Drop (mm)	
0.49	1866	Minimum slope (lower)
0.49	1969	Minimum slope (upper)

Percolation rate = 25750 mm/hr  
50% Percolation rate = **12875 mm/hr**




# INVESTIGATION LOG

Job No.: HD2812  
 No.: ST02  
 Date: 04.04.23  
 Logged By: SW  
 Checked By: RR

Client: Tamahere Country Club  
 Project: Tamahere Country Club PGR  
 Location: -  
 Co-ordinates: 1807559mE, 5809949mN  
 Elevation: Ground

Geology	Geological Interpretation <small>(refer to separate Geotechnical and Geological Information sheet for further information)</small>	Depth (m)	Legend	Scala Penetrometer <small>(Blows / 100 mm)</small>								Vane Shear Strength (kPa) <small>Vane:</small>					Water
				2	4	6	8	10	12	14	16	18	50	100	150	200	
Topsoil	Sandy TOPSOIL; dark blackish brown. Moist; sand, medium.	0.2	TS														
Hinuera Formation	Silty CLAY, with minor sand; greyish brown streaked red brown. Moist; moderate plasticity; sand, fine.	0.6	x														Groundwater Not Encountered
	SAND, with minor clay; brown. Moist; poorly graded; sand, medium.	0.8	.														
	SAND, with trace clay; orange brown. Moist; poorly graded; sand, medium to coarse.	1.0	.														
	Clayey SILT; grey. Moist.	1.2	x														
	SAND; greyish. Moist; poorly graded; sand, fine to medium.	1.4	.														
	Clayey SILT; light grey. Moist; moderate plasticity.	1.8	x														
	SAND, with minor silt; grey. Moist; uniformly graded; sand, fine.	2.0	.														
	EOH: 2.00 m																

Photo	Remarks						
	<p>End of log at 2.0 meters_ Target depth achieved.</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 33%;"><b>Shear Vanes</b></td> <td style="width: 33%;"><b>Water</b></td> <td style="width: 33%;"><b>Investigation Type</b></td> </tr> <tr> <td> <input type="checkbox"/> Peak  <input checked="" type="checkbox"/> Remoulded         </td> <td> <input type="checkbox"/> Standing Water Level  <input type="checkbox"/> Out flow  <input type="checkbox"/> In flow         </td> <td> <input type="checkbox"/> Hand Auger  <input type="checkbox"/> Investigation Pit  <input checked="" type="checkbox"/> Machine Borehole         </td> </tr> </table>	<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>	<input type="checkbox"/> Peak <input checked="" type="checkbox"/> Remoulded	<input type="checkbox"/> Standing Water Level <input type="checkbox"/> Out flow <input type="checkbox"/> In flow	<input type="checkbox"/> Hand Auger <input type="checkbox"/> Investigation Pit <input checked="" type="checkbox"/> Machine Borehole
<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>					
<input type="checkbox"/> Peak <input checked="" type="checkbox"/> Remoulded	<input type="checkbox"/> Standing Water Level <input type="checkbox"/> Out flow <input type="checkbox"/> In flow	<input type="checkbox"/> Hand Auger <input type="checkbox"/> Investigation Pit <input checked="" type="checkbox"/> Machine Borehole					




<b>Job name</b>	Tamahere Country Club
<b>Job number</b>	HD2812
<b>Date</b>	04/04/2023
<b>Plotted by</b>	SW (RR)
<b>Reviewed by</b>	BS

**Perc test results**  
**ST02**

Calculated in general accordance with E1/VM1 - Surface Water, Section 9.0

**Logger depth:** 2.000 m  
**Ground water depth:** NA m

Notes:



**Percolation rate calculation:**

Time (Hour)	Drop (mm)	
2.80	1602	Minimum slope (lower)
3.15	1717	Minimum slope (upper)

Percolation rate = 329 mm/hr  
50% Percolation rate = **164 mm/hr**





# INVESTIGATION LOG

**Job No.:** HD2812  
**No.:** ST03  
**Date:** 29.03.23  
**Logged By:** TD  
**Checked By:** RR

**Client:** Tamahere Country Club  
**Project:** Tamahere Country Club PGR  
**Location:** -  
**Co-ordinates:** 1807643mE, 5809717mN  
**Elevation:** Ground

Geology	Geological Interpretation <small>(refer to separate Geotechnical and Geological Information sheet for further information)</small>	Depth (m)	Legend	Scala Penetrometer <small>(Blows / 100 mm)</small>	Vane Shear Strength (kPa) <small>Vane:</small>	Water
				2 4 6 8 10 12 14 16 18	50 100 150 200 250	
Topsoil	TOPSOIL; dark brown. Moist.	0.0 - 0.2	TS			
Hinuera Formation	SILT; brown. Moist.	0.2 - 0.4	X			
	SAND, with trace silt; light brownish grey. Moist; sand, fine to medium.	0.4 - 0.6	.			
	Clayey SILT; light grey. Moist; low plasticity.	0.6 - 1.0	X			
	Sandy SILT; light grey. Moist; sand, fine.	1.0 - 1.2	.			
	SAND, with trace silt; light grey. Moist; sand, fine to medium.	1.2 - 1.4	.			
	CLAY, with minor silt; light grey. Moist; moderate plasticity.	1.4 - 1.8	X			
	SAND; grey. Wet; sand, fine to coarse.	1.8 - 2.0	.			
	EOH: 2.00 m		2.0			

Groundwater Not Encountered

**Photo**
**Remarks**

End of log at 2.0m. Target depth.

Shear Vanes	Water	Investigation Type
<input type="checkbox"/> Peak <input checked="" type="checkbox"/> Remoulded	<input type="checkbox"/> Standing Water Level <input type="checkbox"/> Out flow <input type="checkbox"/> In flow	<input type="checkbox"/> Hand Auger <input type="checkbox"/> Investigation Pit <input checked="" type="checkbox"/> Machine Borehole




<b>Job name</b>	Tamahere Country Club
<b>Job number</b>	HD2812
<b>Date</b>	29/03/2023
<b>Plotted by</b>	TD (RR)
<b>Reviewed by</b>	BS

**Perc test results**  
**ST03**

Calculated in general accordance with E1/VM1 - Surface Water, Section 9.0

**Logger depth:** 2.000 m  
**Ground water depth:** NA m

Notes:



**Percolation rate calculation:**

Time (Hour)	Drop (mm)	
1.90	1512	Minimum slope (lower)
2.05	1596	Minimum slope (upper)

Percolation rate = 560 mm/hr  
50% Percolation rate = **280 mm/hr**




# INVESTIGATION LOG

Job No.: HD2812  
 No.: ST04  
 Date: 29.03.23  
 Logged By: TD  
 Checked By: RR

Client: Tamahere Country Club  
 Project: Tamahere Country Club PGR  
 Location: -  
 Co-ordinates: 1807469mE, 5809638mN  
 Elevation: Ground

Geology	Geological Interpretation <small>(refer to separate Geotechnical and Geological Information sheet for further information)</small>	Depth (m)	Legend	Scala Penetrometer <small>(Blows / 100 mm)</small>	Vane Shear Strength (kPa) <small>Vane:</small>	Water
				2 4 6 8 10 12 14 16 18	50 100 150 200 250	
Topsoil	TOPSOIL; dark brown. Moist.	0.2	TS			
Hinuera Formation	SILT, with trace sand; light greyish brown. Moist.	0.4	S			
	SAND, with minor silt; light grey. Moist; sand, fine to medium.	0.6	X			
	SAND; grey mottled brown. Moist; sand, fine to coarse.	0.8	X			
	SILT, with trace clay; light grey. Moist.	1.2	S			
	Silty SAND; light greyish brown. Moist; sand, fine.	1.4	X			
	CLAY, with minor silt; light grey streaked orange brown. Moist; moderate plasticity.	1.6	S			
	SAND, with minor silt; greyish brown. Moist; sand, fine.	1.8	X			
	SAND, with minor silt; greyish brown. Moist; sand, fine.	2.0	X			
EOH: 2.00 m						

Groundwater Not Encountered

Photo	Remarks						
	<p>End of log at 2.0m. Target depth.</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 33%; border: none;"><b>Shear Vanes</b></td> <td style="width: 33%; border: none;"><b>Water</b></td> <td style="width: 33%; border: none;"><b>Investigation Type</b></td> </tr> <tr> <td style="border: none;"> <ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Remoulded</li> </ul> </td> <td style="border: none;"> <ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: lightblue; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> In flow</li> </ul> </td> <td style="border: none;"> <ul style="list-style-type: none"> <li><input type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input checked="" type="checkbox"/> Machine Borehole</li> </ul> </td> </tr> </table>	<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>	<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Remoulded</li> </ul>	<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: lightblue; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> In flow</li> </ul>	<ul style="list-style-type: none"> <li><input type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input checked="" type="checkbox"/> Machine Borehole</li> </ul>
<b>Shear Vanes</b>	<b>Water</b>	<b>Investigation Type</b>					
<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: black; margin-right: 5px;"></span> Peak</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Remoulded</li> </ul>	<ul style="list-style-type: none"> <li><span style="display: inline-block; width: 15px; height: 10px; background-color: lightblue; margin-right: 5px;"></span> Standing Water Level</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> Out flow</li> <li><span style="display: inline-block; width: 15px; height: 10px; border: 1px solid black; margin-right: 5px;"></span> In flow</li> </ul>	<ul style="list-style-type: none"> <li><input type="checkbox"/> Hand Auger</li> <li><input type="checkbox"/> Investigation Pit</li> <li><input checked="" type="checkbox"/> Machine Borehole</li> </ul>					

Generated with CORE-GS by Gerooc - 17/04/2023 13:36:21




<b>Job name</b>	Tamahere Country Club
<b>Job number</b>	HD2812
<b>Date</b>	29/03/2023
<b>Plotted by</b>	TD (RR)
<b>Reviewed by</b>	BS

**Perc test results**  
**ST04**

Calculated in general accordance with E1/VM1 - Surface Water, Section 9.0

**Logger depth:** 2.000 m  
**Ground water depth:** NA m

Notes:



**Percolation rate calculation:**

Time (Hour)	Drop (mm)
3.25	1521
3.45	1609

Minimum slope (lower)

Minimum slope (upper)

Percolation rate = 440 mm/hr

50% Percolation rate = 220 mm/hr



# INVESTIGATION LOG

Job No.:

HD2812

Client: Tamahere Country Club

No.:

ST05

Project: Tamahere Country Club PGR

Location: -

Date:

04.04.23

Co-ordinates: 1807279mE, 5809507mN

Logged By:

SW

Elevation: Ground

Checked By:

RR

Geology	Geological Interpretation (refer to separate Geotechnical and Geological Information sheet for further information)	Depth (m)	Legend	Scala Penetrometer (Blows / 100 mm)							Vane Shear Strength (kPa) Vane:					Water		
				2	4	6	8	10	12	14	16	18	50	100	150		200	250
Topsoil	TOPSOIL; brown. Moist.																	
Hinuera Formation	SAND, with some silt; brown. Moist; sand, fine to medium.																	
	SAND; light brown. Moist; sand, fine.	-0.2																
	SAND, with some silt; grey streaked orange. Moist; poorly graded; sand, fine.	-0.8																
	SAND; grey. Moist to wet; sand, fine.	-1.0																
	SILT, with minor sand, with trace clay; grey. Wet; moderate plasticity, moderate dilatancy; sand, fine.	-1.6																
	EOH: 2.00 m	-2.0																

Photo

Remarks

End of log at 2.0 meters\_ Target depth achieved.



Shear Vanes

- Peak
- Remoulded

Water

- Standing Water Level
- Out flow
- In flow

Investigation Type

- Hand Auger
- Investigation Pit
- Machine Borehole

Groundwater Not Encountered




<b>Job name</b>	Tamahere Country Club
<b>Job number</b>	HD2812
<b>Date</b>	04/04/2023
<b>Plotted by</b>	SW (RR)
<b>Reviewed by</b>	BS

**Perc test results  
ST03**

Calculated in general accordance with E1/VM1 - Surface Water, Section 9.0

**Logger depth:** 2.000 m  
**Ground water depth:** NA m

Notes:



**Percolation rate calculation:**


Time (Hour)	Drop (mm)	
2.40	1437	Minimum slope (lower)
2.60	1516	Minimum slope (upper)

Percolation rate = 395 mm/hr  
50% Percolation rate = **197 mm/hr**



**Project: HD2812 - Tamahere Country Club**


**Location: 46 Tamahere Drive, Tamahere**





**Project: HD2812 - Tamahere Country Club**

**Location: 46 Tamahere Drive, Tamahere**








**Project: HD2812 - Tamahere Country Club**


**Location: 46 Tamahere Drive, Tamahere**





**Project: HD2812 - Tamahere Country Club**


**Location: 46 Tamahere Drive, Tamahere**






**Project: HD2812 - Tamahere Country Club**

**Location: 46 Tamahere Drive, Tamahere**








**Project: HD2812 - Tamahere Country Club**


**Location: 46 Tamahere Drive, Tamahere**






**Project: HD2812 - Tamahere Country Club**


**Location: 46 Tamahere Drive, Tamahere**







**Project: HD2812 - Tamahere Country Club**  
**Location: 46 Tamahere Drive, Tamahere**









**Project: HD2812 - Tamahere Country Club**


**Location: 46 Tamahere Drive, Tamahere**





**Project: HD2812 - Tamahere Country Club**  
**Location: 46 Tamahere Drive, Tamahere**






# APPENDIX D

## Liquefaction assessment

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m

**F.S. color scheme**


- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction



### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m

**F.S. color scheme**


- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction



### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	3.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	3.00 m	Fill height:	N/A	Limit depth:	10.00 m

**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy


**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction



**Project title : HD2812 - Tamahere Country Club**  
**Location : 46 Tamahere Drive, Tamahere**

### Overall vertical settlements report






**Project title : HD2812 - Tamahere Country Club**

**Location : 46 Tamahere Drive, Tamahere**

### Overall Liquefaction Potential Index report






**Project title : HD2812 - Tamahere Country Club**

**Location : 46 Tamahere Drive, Tamahere**

### Overall Liquefaction Severity Number report




#### LSN color scheme

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

#### Basic statistics

- Total CPT number: 13
- 100% little liquefaction
- 0% minor liquefaction
- 0% moderate liquefaction
- 0% moderate to major liquefaction
- 0% major liquefaction
- 0% severe liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m
Fines correction method:	B&I (2014)	Average results interval:	3
Points to test:	Based on Ic value	Ic cut-off value:	2.60
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT
Peak ground acceleration:	0.25	Use fill:	No
Depth to water table (insitu):	2.00 m	Fill height:	N/A

Fill weight:	N/A
Transition detect. applied:	Yes
$K_{\sigma}$ applied:	Yes
Clay like behavior applied:	Sand & Clay
Limit depth applied:	Yes
Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m

**F.S. color scheme**


- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction



### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (erthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m
Fines correction method:	B&I (2014)	Average results interval:	3
Points to test:	Based on Ic value	Ic cut-off value:	2.60
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT
Peak ground acceleration:	0.25	Use fill:	No
Depth to water table (insitu):	2.00 m	Fill height:	N/A

Fill weight:	N/A
Transition detect. applied:	Yes
$K_{\sigma}$ applied:	Yes
Clay like behavior applied:	Sand & Clay
Limit depth applied:	Yes
Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m


**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m

**F.S. color scheme**


- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy

**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction



### Liquefaction analysis overall plots



**Input parameters and analysis data**

Analysis method:	B&I (2014)	Depth to GWT (earthq.):	2.00 m	Fill weight:	N/A
Fines correction method:	B&I (2014)	Average results interval:	3	Transition detect. applied:	Yes
Points to test:	Based on Ic value	Ic cut-off value:	2.60	$K_{\sigma}$ applied:	Yes
Earthquake magnitude $M_w$ :	5.90	Unit weight calculation:	Based on SBT	Clay like behavior applied:	Sand & Clay
Peak ground acceleration:	0.25	Use fill:	No	Limit depth applied:	Yes
Depth to water table (insitu):	2.00 m	Fill height:	N/A	Limit depth:	10.00 m

**F.S. color scheme**

- Almost certain it will liquefy
- Very likely to liquefy
- Liquefaction and no liq. are equally likely
- Unlike to liquefy
- Almost certain it will not liquefy


**LSN color scheme**

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction



**Project title : HD2812 - Tamahere Country Club**  
**Location : 46 Tamahere Drive, Tamahere**

### Overall vertical settlements report






**Project title : HD2812 - Tamahere Country Club**

**Location : 46 Tamahere Drive, Tamahere**

### Overall Liquefaction Potential Index report






**Project title : HD2812 - Tamahere Country Club**

**Location : 46 Tamahere Drive, Tamahere**

### Overall Liquefaction Severity Number report



#### LSN color scheme

- Severe damage
- Major expression of liquefaction
- Moderate to severe exp. of liquefaction
- Moderate expression of liquefaction
- Minor expression of liquefaction
- Little to no expression of liquefaction

#### Basic statistics

- Total CPT number: 13
- 100% little liquefaction
- 0% minor liquefaction
- 0% moderate liquefaction
- 0% moderate to major liquefaction
- 0% major liquefaction
- 0% severe liquefaction