

Appendix 1



Photo 1 – From entrance gate looking towards wastewater tanks. Admin building visible on the right.



Photo 2: from entrance gate looking towards admin building. Dryer tower visible on the far right.



Photo 3 – from entrance gate looking towards [now empty] construction village. Energy centre and milk reception in distance. Drystore and dryer tower on left.



Photo 4 – On McDonald Rd looking towards entrance gate.



Photo 5: from McDonald Road at entrance gate



Photo 6 – from wastewater tanks looking towards drystore and dryer



Photo 7: from wastewater tanks looking towards entrance gate. Drystore and admin visible on the left.



Photo 8 – photo of site from café on McDonald Road