

6.0 **Slope Stability**
6.1 **Observations on Site and Environs**

The slope of the bank in the vicinity of the proposed house location is approximately 1 in 7.
Slope stability is not considered to be critical.

5.0 **Limitations**

The recommendations and opinions expressed in this report are based on data from the limited number of Scala tests, Field Vane tests and bore holes described above. Inferences about the nature and continuity of sub soils without the vicinity of the boreholes are considered reasonable but cannot be guaranteed.

This report has been prepared for the particular project in the owners brief to us and no responsibility is accepted for the use of any part of this report in other contexts or for any other purposes.

This site investigation and subsequent reporting were carried out on behalf of Quintet Consulting Ltd by:-

R D G James BSc Civil Engineering, MSc Structures, MIPENZ, CPEng (UK), MICE

Signed:



Date:

