

Supplementary Agenda for a meeting of the Te Kauwhata Community Committee to held in the St John Hall, 4 Baird Avenue, Te Kauwhata on **WEDNESDAY, I FEBRUARY 2022** commencing at **7.00pm**.

It is noted that the main agenda was distributed on Wednesday, 26 January 2023 – this is a supplementary agenda with the reports indicated on the original agenda as being under separate cover

7. **SUPPLEMENTARY REPORTS**

7.5 Safety improvement works on Main Road Te Kauwhata

SA

GJ lon CHIEF EXECUTIVE



Open Agenda

To Te Kauwhata Community Committee

Report title | Safety improvement works on Main Road

Te Kauwhata

Meeting date: 1 February 2023

Report author: | Joban Singh, Roading Corridor Engineer

Authorised by: Vishal Ramduny, Strategic Projects Manager

1. Purpose of the report

Te Take moo te puurongo

To inform the Community Committee about the safety improvement work to be done at Main Road Te Kauwhata.

2. Executive summary Whakaraapopototanga matua

Safety improvement work to be done at Main Road, Te Kauwhata, which involves.

- Removal of pedestrian crossing in front of New World, which is currently creating confusion and discouraging people from using the main existing pedestrian crossing.
- 2. In addition, two car parks identified in the attached plan will be removed considering it is the safety concern for the pedestrians as it on blind spot.
- 3. This also needs repainted on the ground to improve the visibility of crossing and cark parks.
- 4. Two new cark parks will be introduced in front and opposite of New World to balance the number of car parks on Main Road, as shown in plan.
- 5. Speed cushions will be installed either side of road crossing to reduce the speed of heavy traffic.
- 6. Last 6 hit-sticks/bollards on west side will be replaced with new ones.
- 7. Direction tactiles indicators to be installed on either side of pedestrian crossing.

3. Background

Koorero whaimaarama

Council has been informed of numerous safety/incident near misses from vehicle reversing from car parks and the vehicle coming downhill from Waeranga Road which are not slowing down to give way to pedestrians on crossing.

Also, two crossing is creating confusion and safety risk for pedestrians.

4. Next steps Ahu whakamua

Council will be engaging with the community for the feedback. Once the plan is approved, quick action will be taken to start the improvement work for community safety.

5. AttachmentsNgaa taapirihanga

Plan including the above-mentioned work is attached with the report.

